

ABSTRACT

A method of producing coated diamond particles includes the steps of providing a combination of a transition metal selected from zirconium, hafnium, niobium and tantalum, an activation metal and uncoated diamond particles, and heat treating the combination in a non-oxidizing atmosphere to cause the activation metal to bond to the diamond particles and the transition metal to form a carbide coating on the diamond particles.